

## WORKOVER PROCEDURE

**WELL NAME:** DINNER 13-32 **DATE:** 3/3/2014  
**LOCATION:**  
Qtr/Qtr: NW/SW Section: 13 Township: 6N Range: 65W  
**COUNTY:** WELD **STATE:** CO **API #:** 05-123-21942

**ENGINEER:** JONATHAN POMERANTZ 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8" 24# @ 396' KB Elevation: 4710'  
Surface Cmt: 270 sx GL Elevation: 4700'  
Long St Csg: 4 1/2" 11.6# @ 7128' TD: 7140'  
Long St Cmt: 266 sx lead + 218 sx spacer + 140 sx tail PBTD: 7117'  
Long St Date: 6/15/2004

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): Niobrara A Perforations 6709' - 6728'  
Perforation Interval (2): Niobrara B Perforations 6835' - 6865'  
Perforation Interval (3): Codell Perforations 7023' - 7038'  
Tubing: 2 3/8" ?# ? Tbg @ 7001' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_  
**COMMENTS:** \_\_\_\_\_

### PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 6650', dump bail 2 sx of cement on top.
- 4) RIH w/ workstring to pump 75 sx balance plug @ 3800'. SI, WOC. RIH. Tag balance plug (approx 3000').
- 5) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 6) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 7) POOH w/workstring to 500'. Pump approx 175 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.