

WORKOVER PROCEDURE

WELL NAME: Wirth #3 **DATE:** 3/12/2015
LOCATION:
Qtr/Qtr: SENE Section: 1 Township: 6N Range: 59W
COUNTY: Morgan **STATE:** CO **API #:** 05-087-07094

ENGINEER: 7 Day Notice Sent:
(Please notify Engineer of any major changes prior to work) Do not start operations until:
Notice Expires:

OBJECTIVE: Re-Enter and Replug

WELL DATA: Surface Csg: 8 5/8" 24# @137' KB Elevation: 4910'
Surface Cmt: 100 sacks cement GL Elevation: 4901'
Long St Csg: None - Dry Hole TD: 6630'
Long St Cmt: TOC Unknown PBTD: 6630'
Long St Date: _____

Plug Info (1) 20 sx @ 6540' - 6480'
Plug Info (2) 15 sx @ Base of Surface
Plug Info (3) 10 sx @ Surface
Plug Info (4) _____

Tubing: _____ Rods: _____
Pump: _____
Misc.: _____

WELL STATUS: P&A 7/24/1968

COMMENTS: No mention of welded cap on surface casing, or if cut below surface. Deepest waterwell depth is 331', Fox Hills is 410'.

PROCEDURE:

- 1) Survey and locate abandoned well, mark with stake.
- 2) Excavate.
- 3) Drill out surface, role hole clean. Verify and tag top of first plug.
- 4) Drill out first plug, role hole clean. Verify and tag top of next plug.
- 5) Drill out second plug, role hole clean.
- 6) Set plug @ 1500' - 1400' w/ 40 sx, set and tag.
- 7) Set surface Plug @ 430' - Surface w/ 245 sx, set and tag.
- 8) POOH RDMO, weld on cap.
- 9) Reclaim surface.