

REENTRY PROCEDURE

WELL NAME: UPRR PAN AM 01 61 **DATE:** 6/26/2013
LOCATION:
 Qtr/Qtr: NWSW Section: 9 Township: 4N Range: 66W
COUNTY: WELD STATE: CO API #: 05-123-07269
ENGINEER: Amanda Beck 7 Day Notice Sent: _____
 (Please notify Engineer of any major Do not start operations until: _____
 changes prior to work) Notice Expires: _____

OBJECTIVE: Reenter and re-plug

WELL DATA: Surface Csg: 8 5/8" 24# 333' KB Elevation: 4736
 Surface Cmt: 300 SX GL Elevation: 4727
 Long St Csg: 7 7/8" open hole to TD TD: 7855
 Long St Cmt: none PBTD: _____
 Long St Date: _____

 Plug Info (1) 25 SX 7625' - 7710'
 Plug Info (2) cement 300' - 525'
 Plug Info (3) 10 sx @ surface
 Plug Info (4) _____

 Tubing: _____ Rods: _____
 Pump: _____
 Misc.: Base Fox Hills 353'

WELL STATUS: Well Abandoned 5/10/71

COMMENTS: Plugging report states: **No mention of welded on cap**

PROCEDURE:

- 1) Survey and locate abandoned well, mark with stake
- 2) Excavate to expose top of surface casing
- 3) Weld 2" collar to top of 8 5/8" surface casing cap. Make up to collar, pneumatic drill with non-sparking bit. Drill out cap venting possible trapped gas.
- 4) Once verified that no gas exists beneath top of surface casing plate, cut off surface casing below plate with torch, dress up smooth.
- 5) Butt weld 8 5/8" casing to dressed cut, bringing threaded end of casing to ground level.
- 6) Make up to 8 5/8" casing, one 8 5/8" collar and 8 5/8" starter well head
- 7) NU flange adaptor and 5k BOP, test BOP.
- 8) NU and RIH with 6 7/8" cone bit, PU 2 7/8" drill collar, 2 7/8" 8.7# tubing, and TIW valve
- 9) Drill out first cement plug inside surface casing, roll hole clean. Verify top of next cement plug inside of surface casing by tagging.
- 10) If unable to verify isolation of surface casing with tag of cement plug, set RBP inside surface casing
- 11) Once isolation of surface casing is established, either with tagging of cement plug or setting of RBP, pressure test surface casing to 200psi
- 12) After pressure test of surface casing, retrieve RBP or continue drill out of cement plug under surface casing shoe.
- 13) Assume pressure under surface casing shoe, roll hole with kill fluid until well dead, or blow down.
- 14) Verify top of next cement plug at 340' by tagging. Continue drill out of cement plug at 340'.
- 15) Assume pressure, roll hole with kill fluid until well dead or blown down.
- 16) Continue RIH, cleaning out with drilling mud or water to 3000'
- 17) TOO H with cone bit, drill collars, and 2 7/8" tubing.
- 18) PU and RIH with mule shoe and 2 7/8" tubing to 3000'.
- 19) RU cement crew and pump a balanced plug of 100sk 15.8 ppg Class G "neat" cement
- 20) POOH to 503' (150' below base of Fox Hills @ 353')
- 21) RU cement crew and pump 192 sxs of 15.8ppg Class G "neat" cement bring cement to surface
- 22) POOH with 2 7/8" tubing. Wait 4 hrs, and tag TOC. If cement has fallen, top off back to surface
- 23) Let cement set over night, verify cement has not settled and is still at surface. RDMO
- 24) Excavate around wellhead to 8' below grade, cut off 8 5/8" casing, weld on cap
- 25) Backfill hole and reclaim surface to original conditions