

## WORKOVER PROCEDURE

**WELL NAME:** SINJIN E36-15 **DATE:** 2/25/2016  
**LOCATION:** Qtr/Qtr: SW/SE Section: 36 Township: 6N Range: 65W  
Footages: &  
**COUNTY:** WELD **STATE:** CO **API #:** 05-123-16308

**ENGINEER:** JOHN HATCH 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8" 23# @366' KB Elevation: 4651'  
Surface Cmt: 300 sx GL Elevation: 4641'  
Long St Csg: 2 7/8" 6.50#, J-55 @ 7035' TD: 7040'  
Long St Cmt: 250 sx PBTD: 6917'  
Long St Date: 11/26/1992

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): Codell Perforations 6873' - 6883'  
Perforation Interval (2): \_\_\_\_\_  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 1.66" 2.30#, J-55 @6852.5' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_  
**COMMENTS:** \_\_\_\_\_

### PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 1.66" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6823', pump 18 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 466'. Pump 176 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. RDMOL.