

**WORKOVER PROCEDURE**

**WELL NAME:** WADSWORTH 36-15 **DATE:** 4/5/2016

**LOCATION:** Qtr/Qtr: NW/NE Section: 36 Township: 7N Range: 67W

Footages: 1319' FNL & 1520' FEL

**COUNTY:** WELD **STATE:** CO **API #:** 05-123-25811

**ENGINEER:** Jonathan Pomerantz 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major changes prior to work) Do not start operations until: \_\_\_\_\_  
Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8" 24# @ 471' KB Elevation: 4886'  
Surface Cmt: 450 sx GL Elevation: 4875'  
Long St Csg: 4 1/2" 11.6# @ 7496' TD: 7503'  
Long St Cmt: 1386 sx PBDT: 7492'  
Long St Date: 6/4/2008

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): Codell Perforations 7398' - 7416'  
Perforation Interval (2): \_\_\_\_\_  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 2 3/8" ?# ? tbg @ 7385' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_

**COMMENTS:** \_\_\_\_\_

**PROCEDURE:**

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RIH w/ workstring and tubing-set CIBP. Set CIBP @ 7348'. Pump 35 sx on top of CIBP.
- 4) POOH w/ workstring to 2500'. Pump 20 sx courtesy plug. If maintain circulation, no need to tag plug.
- 5) POOH w/ workstring to 675'. Pump 10 sx balance plug. If maintain circulation, no need to tag plug.
- 6) RU WL. RIH w/ perf gun. Perforate 4 1/2" casing @ 520'. POOH w/ perf gun. RD WL.
- 7) Pump 175 sx shoe plug down the 4 1/2" casing. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.