

WORKOVER PROCEDURE

WELL NAME: ROUKEMA 05-01 **DATE:** 5/6/2016
LOCATION:
Qtr/Qtr: SW/SW Section: 5 Township: 4N Range: 64W
Footages: 650' FSL & 650' FWL
COUNTY: WELD **STATE:** CO **API #:** 05-123-11909

ENGINEER: Jonathan Pomerantz 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 405' KB Elevation: 4775'
Surface Cmt: 165 sx GL Elevation: 4763'
Long St Csg: 4 1/2" 11.6# @ 7135' TD: 7140'
Long St Cmt: 170 sx PBTD: 7090'
Long St Date: 7/31/1984

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Codell Perforations 7016' - 7030'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 2 3/8" 4.7# J-55 tbg @ 7005' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RIH w/ workstring and tubing-set CIBP. Set CIBP @ 6966'. Pump 30 sx on top. POOH w/ workstring.
- 4) Unland casing. Cut casing off @ 2500'. POOH w/ casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 540'. Pump 225 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.