

WORKOVER PROCEDURE

WELL NAME: UPV 23-08H6 **DATE:** 10/11/2016

LOCATION: Qtr/Qtr: SW/NE Section: 23 Township: 5N Range: 66W

Footages: 2007 FNL & 2605 FEL

COUNTY: WELD **STATE:** CO **API #:** 05-123-18628

ENGINEER: JOHN HATCH 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24#, grade ? @ 419' KB Elevation: 4872'
Surface Cmt: 125 sx GL Elevation: 4860'
Long St Csg: 3 1/2" 7.70#, grade? @ 7872' TD: 7879'
Long St Cmt: 100 sx PBTD: 7814'
Long St Date: 12/1/1994

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 7369' - 7585'
Perforation Interval (2): Codell Perforations 7690' - 7704'
Perforation Interval (3): _____
Tubing: 2 1/16" 3.25#, J-55 @ 7668' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____

COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 1/16" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 7319', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 654'. Pump 219 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. RDMOL.