

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/10/2022

Submitted Date:

05/17/2022

Document Number:

702000248

**FIELD INSPECTION FORM**

Loc ID 313288 Inspector Name: Waldron, Emily On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 3975  
Name of Operator: ARGALI EXPLORATION COMPANY  
Address: PO BOX 416  
City: RANGELY State: CO Zip: 81648

**Findings:**

- 9 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
		dnr_cogccengineering@state.co.us	
General, Contact		argaliexplorationcompany@gmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284611	WELL	SI	03/10/2015	GW	081-07302	SIMPSON 24-11	SI

**General Comment:**

Routine compliance follow up inspection. Follow up to inspection from 8/12/2021 document number 689806231. Bradenhead has been installed. Compliance issues remaining:  
well is overdue for MIT  
holes in produced water tank  
Compliance issues observed during this inspection:  
culvert on access road overwhelmed, road damaged, sediment transported across and off access road

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Tank label peeling.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Battery sign knocked over.		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	970-629-1906 970-629-2614	Date:	
Corrective Action:		Date:	

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Knocked over tank and other equipment parts becoming debris.		
Corrective Action:	Comply with Rule 606.	Date:	06/17/2022

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type			corrective date
Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Gas Meter Run	# 1		
Comment:	Building only, no equipment in housing.		
Corrective Action:		Date:	
Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		
Comment: <b>Holes in tank.</b>					
Corrective Action: <b>Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.</b>					Date: <b>09/16/2021</b>

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 284611 Type: WELL API Number: 081-07302 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

**Comment:** Well is overdue for Mechanical Integrity Test. Well has been shut-in since previous MIT in 2013.  
MIT requires 10-day notification via Form 42.  
Well plugging requires an approved Form 6 Intent to Abandon to Plug Well.

**Corrective Action:** Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Date: 09/30/2021

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Culvert on access road has been overwhelmed. The road has been damaged and there is evidence of sediment being transported across and off access road.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.\(2\)C](#)

Date: 05/19/2022

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403052461	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5756360">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5756360</a>
702000252	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5756352">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5756352</a>