

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/25/2022

Submitted Date:

06/01/2022

Document Number:

702800263**FIELD INSPECTION FORM**Loc ID 314510 Inspector Name: O'Malley, Anna On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 16700Name of Operator: CHEVRON USA INCAddress: 760 HORIZON DRIVE STE 401City: GRAND JUNCTION State: CO Zip: 81506**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Olson, Andrew		AndrewOlson@chevron.com	Principle Agent Wilson Creek
Heil, John		john.heil@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Puechner, Rachel		RPuechner@chevron.com	Decommissioning Advisor Wilson Creek

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
314510	LOCATION	AC			-	WILSON CREEK UNIT-63N94W 34NENW	RI

General Comment:

On 05/25/2022, Reclamation Specialist O'Malley conducted a follow up inspection to #702800180 at Chevron USA Inc's Wilson Creek Unit-63N94W /34NENW Location #314510 in Rio Blanco County, Colorado. West Environmental Supervisor, Alex Fischer was also present for the inspection.

The following compliance issues were observed during this inspection:

- Stormwater: BMPs to manage stormwater in disrepair

Refer to the "Location" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type WELLHEAD

Comment: Previous inspection #702800180 observed that the area around the well has been excavated. Fence panels were present, but do not completely enclose the excavated area. Inspector required Operator to Comply with Rule 913.b.(5).B.i by 5/24/22.

It was observed in this inspection that fence panels were present completely enclosing the excavation around the well. This corrective action has been addressed.

Corrective Action: Date: **Equipment:**

corrective date

Type: Other

#

Comment: Previous inspection #702800180 observed that the area around the well has been excavated. The sides of the pit are steep and may not allow for escape by wildlife. BMPs to ensure wildlife egress not observed. Inspector required Operator to install or repair BMPs to enable egress from the excavated area by 5/12/22.

It was observed in this inspection that the sides of the excavation have been modified. The slope is gentle enough to allow for wildlife egress. Fence panels are present, completely enclosing the excavation. This corrective action has been addressed.

Corrective Action: Date: **Venting:**

Yes/No

Comment: Corrective Action: Date: **Flaring:**

Type

Comment: Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles	Fail					

Comment: Previous inspection #702800180 observed excavated soil from around the well stored on Location without BMPs to prevent the E&P waste from migrating off the Location. Inspector required Operator to comply with Rule 913.b.(5).B.i-v by 5/12/22.

It was observed in this inspection that a straw wattle has been installed around the perimeter of the soil pile. This corrective action has been addressed.

It was observed in this inspection that the straw wattle on the northwestern perimeter of the Location is in disrepair and not in proper functioning condition to minimize erosion, transport of sediment and offsite degradation.

Corrective Action: Install or repair required BMPs per Rule 1002.f. Continue to monitor and manage stormwater on the Location. Ongoing stormwater management is required until the site receives a passing final inspection.

Date: 06/15/2022

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403065287	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5768424
702800264	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5768423