

WORKOVER PROCEDURE

WELL NAME: FRY 18-01 DATE: 7/24/2012

LOCATION: Qtr/Qtr: SWNW Section: 18 Township: 4N Range: 64W

COUNTY: WELD STATE: CO API #: 05-123-11362

ENGINEER: LEAH PERKINS 7 Day Notice Sent:
(Please notify Engineer of any major changes prior to work) Do not start operations until:
Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 209' KB Elevation: 4810
Surface Cmt: 130 sx GL Elevation: 4795
Long St Csg: 4 1/2" 11.60# @ 7190' TD: 7190
Long St Cmt: 160 sx TOC @ 6520' PBTD: 7131
Long St Date: 9/20/1983

Plug Back (Sand or CIBP): Sand plug 7131' - 7190'
Perforation Interval (1): Codell Perfs 7089' - 7102'
Perforation Interval (2):
Perforation Interval (3):
Tubing: 2 3/8" 4.70# J-55 225 jts bottom @ 7082' Rods:
Pump:
Misc.: TOC @ 6520'

PRODUCTION STATUS:
COMMENTS:

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
2) POOH w/ 2 3/8" tubing. And lay down.
3) RU WL. RIH w/CIBP. Set CIBP @ 6989', dump bail 2 sx of cement on top.
4) Unland casing. Cut casing off +/- 6350'. POOH with casing laying down on trailer.
5) RIH w/ workstring to 6350' Pump 100 sx stub plug. Wait 4 hrs, tag plug.
6) Pump 50 sx courtesy plug @2500'. POOH w/workstring to 310'. Pump approx 215 sx shoe plug, cement to surface.
6) RIH. Tag shoe plug. Add additional cement if needed.
7) POOH w/workstring laying down. Cut surface casing off 6'-8' below ground.
8) Clean up location. Reclaim location. RDMO.