

WORKOVER PROCEDURE

WELL NAME: SITZMAN E23-13 **DATE:** 1/29/2013

LOCATION: Qtr/Qtr: SWSW Section: 23 Township: 6N Range: 65W

COUNTY: WELD **STATE:** CO **API #:** 05-123-17855

ENGINEER: LEAH PERKINS **7 Day Notice Sent:** _____
(Please notify Engineer of any major **Do not start operations until:** _____
changes prior to work) **Notice Expires:** _____

OBJECTIVE: P&A

| | | |
|-------------------|---|---------------------------|
| WELL DATA: | Surface Csg: <u>8 5/8" 24# @329'</u> | KB Elevation: <u>4720</u> |
| | Surface Cmt: <u>215 sx</u> | GL Elevation: <u>4710</u> |
| | Long St Csg: <u>2 7/8" 6.5# @ 7150'</u> | TD: <u>7150</u> |
| | Long St Cmt: <u>250 sx</u> | PBTD: <u>7064</u> |
| | Long St Date: <u>2/2/1994</u> | |

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Codell Perforations 7004' - 7019'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 1 1/4" 2.3# J-55 @ 6979' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 1 1/4" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 6904', dump bail 2 sx of cement on top.
- 4) RIH w/ workstring. Pump 10 sx plug @ 2500'. If maintain circulation do not need to tag plug.
- 5) POOH w/workstring to 500'. Pump approx 25 sx shoe plug. Cement to surface.
- 6) RIH. Tag shoe plug. Add cement if needed.
- 7) Cut surface casing off 6'-8' below ground.
- 8) Clean up location. Reclaim location. RDMO.