

WORKOVER PROCEDURE

WELL NAME: LOLOFF 2 **DATE:** 1/30/2015
LOCATION:
Qtr/Qtr: SW/SW Section: 26 Township: 5N Range: 64W
Footages: 660 FSL & 660 FWL
COUNTY: WELD **STATE:** CO **API #:** 05-123-11069

ENGINEER: DARYL KVEDER 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8-5/8" 23# J-55 @ 316' KB Elevation: 4676
Surface Cmt: 290 sx GL Elevation: 4663
Long St Csg: 4-1/2" 11.6# N-80 @ 6994' TD: 6870
Long St Cmt: 225 sx PBTD: 6855
Long St Date: _____

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations (6545-6703')
Perforation Interval (2): Codell Perforations (6802-6812')
Perforation Interval (3): _____
Tubing: 2-3/8" 4.70# J-55 @ 6783.24' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: Shut-in / not producing
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6495', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 125 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 416'. Pump 300 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.