

WORKOVER PROCEDURE

WELL NAME: Buckmur #B02-25 **DATE:** 3/22/2016
LOCATION:
Qtr/Qtr: NESW Section: 2 Township: 5N Range: 64W
Footages: 1357' FSL & 1318' FWL
COUNTY: WELD **STATE:** CO **API #:** 05-123-23290

ENGINEER: Johnathan Pomerantz (Noble - 303-228-4198) 7 Day Notice Sent: _____
Tanner Boyd - (Halliburton - 432-803-6064) Do not start operations until: _____
(Please notify Engineer of any major changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8.625" 24# (Grade ?) SET AT 589' KB Elevation: 4624'
Surface Cmt: 445 sx GL Elevation: 4612'
Long St Csg: 4.5" 11.6# N-80 SET AT 6883' TD: 6900'
Long St Cmt: 630 sx PBTD: 6837'
Long St Date: 10/29/2005

Plug Back (Sand or CIBP): _____
Perforation Interval (1): NIOBRARA Perforations 6478' - 6598'
Perforation Interval (2): CODELL Perforations 6762' - 6776'
Perforation Interval (3): _____
Tubing: 2.375" 4.7# @ 6749' Rods: NA
Pump: NA
Misc.: **SPUD DATE:** 10/24/2005 **TD DATE:** 10/28/2005

PRODUCTION STATUS: _____
COMMENTS: State shows ground elevation as 4620'
No Sussex Production within a mile

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2-3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP at 6428', dump bail 2 sx of cement on top.
- 4) Perforate at 2500' and 689'.
- 5) Set CICR at 2400'.
- 6) RIH with CT and sting into CICR. Pump 87 sx cement below retainer, leaving 100' (8 sx) on top of CICR.
- 7) POOH and RD CT. Pump 250 sx (198 sx out & 52 sx in) shoe plug down production casing. Bring cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.