

## WORKOVER PROCEDURE

**WELL NAME:** Bashor State AA16-03 **DATE:** 11/16/2016  
**LOCATION:**  
Qtr/Qtr: NENW Section: 16 Township: 6N Range: 63W  
Footages: 595' FNL & 2040' FWL  
**COUNTY:** WELD **STATE:** CO **API #:** 05-123-26119

**ENGINEER:** Narayan Choudhary 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8" 24# J-55 @ 743' KB Elevation: 4694'  
Surface Cmt: 320 sks GL Elevation: 4681'  
Long St Csg: 4 1/2" 11.6# M-80 @ 6841' TD: 6867'  
Long St Cmt: 410 sks PBTD: 6813'  
Long St Date: 8/12/2007

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): Niobrara Perforations 6487' - 6598'  
Perforation Interval (2): Codell Perforations 6740' - 6750'  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 2 3/8" 4.7# J-55 @ 6719' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** SI  
**COMMENTS:** \_\_\_\_\_

### PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6437', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2180'. POOH w/ casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled (top of plug 1950'). If maintain circulation, no need to t
- 6) POOH w/ workstring to 843'. Pump 262 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.