

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/28/2023

Submitted Date:

06/29/2023

Document Number:

708200365

**FIELD INSPECTION FORM**Loc ID 317118 Inspector Name: Edwardson, Dylan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10690

Name of Operator: IMPETRO RESOURCES LLC

Address: 558 CASTLE PINES PKWY UNIT B-4

City: CASTLE PINES State: CO Zip: 80108

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

10 Number of Comments

8 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Bongers, Brent	361-935-5633	bbongers@impetroresources.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
236500	WELL	SI	01/01/2023	OW	121-08990	WRIGHT 1	RI
317118	LOCATION	AC			-	WRIGHT-63S54W 1SWNW	RI

**General Comment:**[This is an Interim Reclamation and Stormwater Inspection for Location ID 317118.](#)

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	NFPA Placards at day tank (wellhead), propane tank, and separator shed are cracked, peeling, faded, and/or not legible.		
Corrective Action:	Install sign to comply with Rule 605.g. Corrective action date is the date the location was observed out of compliance.	Date:	06/28/2023
Type	WELLHEAD		
Comment:	No sign posted at pump jack/wellhead (only emergency contact # observed).		
Corrective Action:	Install sign to comply with Rule 605.d. Corrective action date is the date the location was observed out of compliance.	Date:	06/28/2023

Emergency Contact Number:

Comment:

Corrective Action:  Date:

**Good Housekeeping:**

Type	OTHER		
Comment:	Guy line anchors not properly marked.		
Corrective Action:	Install proper guy line markers per Rule 1003.a. Corrective action date is the date the location was observed out of compliance.	Date:	06/28/2023
Type	OTHER		
Comment:	Stained soil observed around wellhead, battery, and pit walls.		
Corrective Action:	Properly dispose of oily waste in accordance with 905.e. Corrective action date is the date the location was observed out of compliance.	Date:	06/28/2023
Type	DEBRIS		
Comment:	Debris observed scattered throughout the pit walls/berms.		
Corrective Action:	Comply with Rule 606 and remove all debris. Corrective action date is the date the location was observed out of compliance.	Date:	06/28/2023

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Equipment:</b>			corrective date
Type: Other	#		
Comment:	No wildlife protection equipment observed at secondary containment (day tank at wellhead) or at the partially buried tank vent tube.		
Corrective Action:	Install or repair wildlife protection equipment per Rule 902.b. Corrective action date is the date the location was observed out of compliance.		Date: 06/28/2023

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	236500	Type:	WELL	API Number:	121-08990	Status:	SI	Insp. Status:	RI
Facility ID:	317118	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	RI

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

- 1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_
- 1003c. Compacted areas have been cross ripped? \_\_\_\_\_
- 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_
- Cuttings management: \_\_\_\_\_
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_
- Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

## RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_ F \_\_\_\_\_

Comment

This location does not comply with Rule 1003. During this inspection, Staff observed that undesirable vegetation, including Colorado Noxious Weeds, were observed throughout the well location and production areas. Kochia, russian thistle, canada thistle (List B) and cheatgrass (List C) were among the species observed and will need to be actively managed during this growing season to prevent spread onto adjacent lands. Refer to attached inspection photos.

Corrective Action

Perform reclamation in accordance to Rule 1003. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until the location meets Rule 1003 standards. Corrective action date is the date the location was observed out of compliance.

Date **06/28/2023**Overall Interim Reclamation **Fail****Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: Corrective Action: 

Date \_\_\_\_\_

Overall Final Reclamation

Well Release on Active Location ☐Multi-Well Location ☐**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: This location does not comply with Rule 1002.f. Evidence of rill erosion was observed on the pit walls/berms with off-location sediment transport apparent. Additionally, further rilling was observed around the wellhead and next to the northwest guy line anchor. Additional maintenance and/or implementation of stormwater BMPs is required in order for the location to come into compliance. Refer to attached inspection photos.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C. Corrective action date is the date the location was observed out of compliance, as the location should be in compliance at all times.

Date: 06/28/2023

Pits: ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403450093	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6165566">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6165566</a>
708200366	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6165539">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6165539</a>