

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:

04/22/2014

Document Number:

667500252

Overall Inspection:

ACTION REQUIRED**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	203278	320259	AXELSON, JOHN	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 27635Name of Operator: ENERGY SEARCH COMPANYAddress: 12101 EAST 2ND AVENUE #100City: AURORA State: CO Zip: 80011

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☒ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Robuck, Don		DON_Roebuck@MSN.COM	
Mark Stonehocker		markstonehocker@gmail.com	
JOHNSON, RANDELL		randell.johnson@state.co.us	
Marisco, Joe		joemarisco@yahoo.com	

Compliance Summary:

QtrQtr:	NESE	Sec:	7	Twp:	1S	Range:	67W
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
12/17/2013	600000442	PR	SI	ACTION REQUIRED	P		No
12/16/2013	600000436	PR	SI	ACTION REQUIRED	P		No
02/10/2012	656500171			ACTION REQUIRED	P		No
07/01/2010	200266925	PR	PR	SATISFACTOR Y			Yes
10/28/2008	200201165	PR	PR	ACTION REQUIRED			Yes
05/26/2005	200071531	PR	PR	ACTION REQUIRED		Fail	Yes
07/24/1997	500133054	PR	PR			Pass	No

Inspector Comment:

Inspection performed to investigate surface owner complaint #200402861 regarding accumulations of oil at wellhead/pumping unit. Also follow up to inspection doc#600000442 performed on 12/17/13. Several corrective actions were required on previous inspection to be completed by 5/30/14 included signage for containers at wellhead, cleanup accumulations of oily waste and lube oil at pumping unit and wellhead, cleanup spills at battery, provide appropriate signage on tanks at battery, mark deadman and remediate piles of contaminated soils. Corrective actions were not completed.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203278	WELL	PR	02/29/2008	OW	001-08787	WIEMAN 5	PR

Equipment:**Location Inventory**

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Signs/Marker:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
BATTERY	ACTION REQUIRED	Battery sign does not list the wells serviced by the facility	Install sign to comply with rule 210.	05/31/2014
TANK LABELS/PLACARDS	ACTION REQUIRED	water tank does not have capacity labelled	Install sign to comply with rule 210.	05/31/2014

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
Crude Oil	Tank	<= 5 bbls	Oil saturated material in northwest corner of battery. Remediate contaminated material.	05/31/2014
Crude Oil	Pump Jack	<= 5 bbls	Oil saturated material at wellhead and surrounding pumping unit.	05/31/2014

☒ Multiple Spills and Releases?**Fencing/:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
PUMP JACK	SATISFACTORY			

Inspector Name: AXELSON, JOHN

Facilities:		<input type="checkbox"/> New Tank		Tank ID: _____	
Contents	#	Capacity	Type	SE GPS	
PRODUCED WATER			FIBERGLASS AST		
S/AV:	ACTION REQUIRED		Comment: Residual oil on exterior of tank. Lid cover not seated.		
Corrective Action:		Clean residual oil of outside surface of tank. Repair tank cover.			Corrective Date: 05/31/2014
Paint					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Insufficient	Base Insufficient	Adequate	
Corrective Action				Corrective Date	
Comment					
Venting:					
Yes/No	Comment				
Flaring:					
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date	

Predrill

Location ID: 203278

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Environmental****Spills/Releases:**

Type of Spill: OIL Description: _____ Estimated Spill Volume: _____

Comment: Unknown if reportable quantities. Accumulations of oil at wellhead and surrounding pumping unit. Appears fresh dirt is being used to cover oil at wellhead. Oil saturated material located in northwest corner of battery within bermed area. Remove all oily waste, collect confirmation samples to verify compliance with Table 910-1 standards. Submit Form 27 with soil disposal documentation and sample results no later than 5/31/2014.

Corrective Action: Cleanup all oily waste at wellhead, pumping unit & battery. Date: 05/31/2014

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Complaint:

Tracking Num	Category	Assigned To	Description	Incident Date
200402862	OTHER	AXELSON, JOHN	Equipment failure at the Wierman #5 pump motor has spilled a significant amount of motor / cooling oil onto the surface of the ground. This oil has saturated the surface of the ground and appears to have penetrated deep below the surface of the ground contaminating the soil and potentially the water. I am requesting that the COGCC take environmental samples of the subsurface of the soil to determine the extent of the leak. Then require the operator to clean site, and repair equipment so no additional leaking occurs.	04/23/2014

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____
 CA _____ CA Date _____
 Waste Material Onsite? _____ CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? _____ CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Inspector Name: AXELSON, JOHN

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
667500254	Produced water tank cover opening	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3334718
667500255	Residual oil on water tank	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3334719
667500256	Oil saturated material NW corner of bermed area	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3334720
667500257	Oil staining at wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3334721
667500258	Oil surrounding pumping unit	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3334722

667500259	Oil leaking at lube oil tank - no containment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3334723