

Kimball Creek 14-2D1-995

Inspection DOC# 675200264

Erosion and rilling
along cut slope.



Erosion and rilling
along cut slope.



Subsidence over lines
from wellhead to
separator.



One condensate tank
missing capacity and
operator name.

