

Site Photos: API# 05-073-06278

Date: November 20, 2014



photo 1: Looking North at the location from the access road.



photo 2: Stegas 34-15 #2

Site Photos: API# 05-073-06278

Date: November 20, 2014



photo 3: Soil stockpiles at the West side of location.



photo 4: Top soil stockpile is being eroded and is not being protected from degradation.

Site Photos: API# 05-073-06278

Date: November 20, 2014



photo 5: Southwest corner of location. Weed growth (Russian thistle) around top soil stockpile.



photo 6: South side of location facing North toward production equipment.

Site Photos: API# 05-073-06278

Date: November 20, 2014



photo 7: Weed growth (kochia) around top soil stockpiles at the East side of location..



photo 8: Southeast corner of location facing Northwest.

Site Photos: API# 05-073-06278

Date: November 20, 2014



photo 9: Tanks appear to be correctly labeled as required by previous inspection.



photo 10: Tanks appear to be correctly labeled as required by previous inspection.