

## Final Reclamation Inspection



**Photo 1.** Photo taken from southern location, facing West. Location is being used by private landowner as a horse mucking area. Area has *Kochia* sp. growing throughout area. No stormwater controls in place. Appears there could be runoff into the pond down slope of the location.

## Final Reclamation Inspection



**Photo 2.** Photo taken from southern location, facing North. Location is being used by private landowner as a horse mucking area. Area has *Kochia* sp. growing throughout area. No stormwater controls in place. Appears there could be runoff into the pond down slope of the location.



## Final Reclamation Inspection



**Photo 3.** Photo taken from northern location, facing South. Location is being used by private landowner as a horse mucking area. Area has *Kochia* sp. growing throughout area. No stormwater controls in place. Appears there could be runoff into the pond down slope of the location.

## Final Reclamation Inspection



**Photo 4.** Photo taken from southern location, facing North. Photo demonstrates Kochia sp. growing throughout area. No stormwater controls in place. Appears there could be runoff into the pond down slope of the location.