



Photo#1: Overview of Location to SW.



Photo#2: Equipment/Supplies stored on NE portion of Location, subject of Variance request.



Photo#3: Ground conditions where supplies in previous Photo are Located. Area is compacted and stabilized.



Photo#4: Kochia and Cheat Grass are thriving on the compacted areas.



Photo#5: Tank in storage area on Location. Kochia has senesced and become Debris.



Photo#6: View of Storage Area to NE.

March 4, 2016

Inspection Photos WPX Potter Loc# 335172



Photo#7: Slash pile in what appears to be un reclaimed Interim Reclamation area along North side of Location. Arrow in background indicates Manure Layer in next Photo.



Photo#8: Heavy Tracked Manure Layer, West of Slash pile in previous Photo. Part of Revegetation Project? View to SW



Photo#9: View of Manure Layer to NE.

March 4, 2016

Inspection Photos WPX Potter Loc# 335172



Photo#10: Fresh manure/bedding pile at West end of layered manure strip.



Photo#11: Un reclaimed area along South side of Location.

March 4, 2016

Inspection Photos WPX Potter Loc# 335172



Photo#12: Cut slope area in back of Separators; senesced Vegetation has become Debris.



Photo#13: Unidentified Drainage Pipe/Riser located off North edge of Location.