

Construction Inspection



Photo 1. Photo taken from entrance of location, facing South. Culverts installed at entrance.

Construction Inspection



Photo 2. Photo taken from entrance of location, facing North. Culverts installed at entrance.

Construction Inspection



Photo 3. Photo taken from northwest location, facing South. Stormwater BMP installed in center of photo.

Construction Inspection



Photo 4. Photo taken from southwest location, facing East. Stormwater BMP installed in center of photo.

Construction Inspection



Photo 5. Photo taken from southeast location, facing North. Stormwater BMP installed in center of photo.

Construction Inspection



Photo 6. Photo taken from northeast location, facing West. Stormwater BMP installed in center of photo.

Construction Inspection



Photo 7. Photo taken from northern location, facing West. Stormwater BMP installed in center of photo.

Construction Inspection



Photo 8. Photo taken from eastern location, facing West. Topsoil salvage in process.

Construction Inspection



Photo 9. Photo taken from northwest location, facing South. Topsoil stockpile in center of photo. Topsoil stockpile needs to be stabilized upon completion of salvage process.