

## Final Reclamation Inspection



**Photo 1.** Photo taken from eastern location, facing West. Cut slopes still present that are stabilized with vegetation but rill erosion is occurring along portions of the cut slope.



## Final Reclamation Inspection



**Photo 2.** Photo taken from eastern location, facing West. Uniform native, perennial vegetation established throughout most of location.



## Final Reclamation Inspection



**Photo 3.** Photo taken from southeast location, facing South. Equipment at location and rill erosion occurring which is forming into gully erosion overtime.



## Final Reclamation Inspection



**Photo 4.** Photo taken from approximate northern location. Equipment left at location.



## Final Reclamation Inspection



**Photo 5.** Photo taken from eastern location, facing West. Equipment left at location.