



Photo#1: Overview of Location to SW.

June 18, 2016

Inspection Photos: Potter Loc#335172.



Photo#2: Equipment / Supplies stored on NE portion of Location. Kochia has senesced and become Debris.

Inspection Photos: Potter Loc#335172.

June 18, 2016





Photo#3: Slash/Debris pile in Interim Reclamation area along North side of Location

Inspection Photos: Potter Loc#335172.

June 18, 2016





Photo#4: Interim Reclamation Area#1 has had more manure dumped since previous Inspection on what Operator said was seeded Interim Reclamation.

Inspection Photos: Potter Loc#335172.

June 18, 2016





Photo#5: Kochia is only successful Vegetation in the heavily Manured area.

Inspection Photos: Potter Loc#335172.

June 18, 2016





Photo#6: Interim Reclamation Area#2 at SW end of Location is predominately a Monoculture of Cheat grass.

Inspection Photos: Potter Loc#335172.

June 18, 2016





Photo#7: Wattles running East to West at NW perimeter of Location

Inspection Photos: Potter Loc#335172.

June 18, 2016





Photo#8: Water is undercutting wattles at multiple sites.

Inspection Photos: Potter Loc#335172.

June 18, 2016





Photo#9: Water is undercutting wattles at multiple sites.

Inspection Photos: Potter Loc#335172.

June 18, 2016





Photo#10: Further erosion and Channeling after undercutting of Wattles.

Inspection Photos: Potter Loc#335172.

June 18, 2016





Photo#11: Run off is draining to water bodies immediately adjacent to River.

Inspection Photos: Potter Loc#335172.

June 18, 2016





Photo#12: Manure / Bedding piled at NW corner of Location.

Inspection Photos: Potter Loc#335172.

June 18, 2016





Photo#13: Scotch Thistle is establishing in scattered sites in perimeter areas of Location.

Inspection Photos: Potter Loc#335172.

June 18, 2016





Photo#13: Interim Reclamation Areas identified in Inspection.

Inspection Photos: Potter Loc#335172.

June 18, 2016