

Pictures were taken during field inspection of spill area on 8/11/2016.



This erosion area was between the flowline and siphon 43 impoundment. No hydrocarbon was observable in this area.





Photo taken at spill release point. Area with excavator is at siphon 43.





Yellow flag is marking the flowline. This was point of discharge.