

## Interim Reclamation Inspection- Overview



Aerial imagery taken September 2015 using COGCC GISOnline database, illustrating KPK and Kerr McGee shared tank battery location in relation to a corrective action to fix a portion of the access road that was widened by an operator.

# Interim Reclamation Inspection



**Photo 1.** Photo taken west of the batteries, facing North. Corrective actions to repair ruts have been performed.



## Interim Reclamation Inspection



**Photo 2.** Photo taken west of the batteries, facing South. Corrective actions to repair ruts have been performed.

## Interim Reclamation Inspection



**Photo 3.** Photo taken north of the shared tank battery location, facing North along the access road. Need to repair access road that was widened by an operator and re-seed any portions that are disturbed during this process.