

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/27/2016

Submitted Date:

10/31/2016

Document Number:

685301670**FIELD INSPECTION FORM**
 Loc ID 313621 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 46685Name of Operator: KINDER MORGAN CO2 CO LPAddress: 1001 LOUISIANA ST SUITE 1000City: HOUSTON State: TX Zip: 77002**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|--------------|---------------------------------|-----------------------|
| Labowskie, Steve | | steve.labowskie@state.co.us | COGCC |
| Conway, James | 970-882-5505 | james_conway@kindermorgan.com | SW Inspection Reports |
| Swift, Barry | 970-882-5545 | barry_swift@kindermorgan.com | SW Inspection Reports |
| Millican, Chris | 970-882-5504 | chris_millican@kindermorgan.com | SW Inspection Reports |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 295333 | WELL | PR | 06/06/2007 | STRT | 083-06646 | HF 3 | PR |

General Comment:

Location**Lease Road:**

| | | | |
|--------------------|--------|-------|--|
| Type | Access | | |
| comment: | | | |
| Corrective ActionL | | Date: | |

Overall Good: ☐**Signs/Marker:**

| | | | |
|--------------------|----------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | |
|--------------------|--|-------------|
| Comment: | | |
| Corrective Action: | | Date: _____ |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|---------------|-------|--|
| Type | LOCATION | | |
| Comment: | Post and Wire | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|---------------------------|----------|-------|-----------------|
| Type: Ancillary equipment | # 1 | | corrective date |
| Comment: | Wellhead | | |
| Corrective Action: | | Date: | |
| Type: Flow Line | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 295333 | Type: | WELL | API Number: | 083-06646 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | PR | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | Waddles | Pass | | | |
| | | Culverts | Pass | | | |
| | | Gravel | Pass | | | |
| Compaction | Pass | Compaction | Pass | | | |
| Gravel | Pass | Check Dams | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------|---|
| 685301670 | INSPECTION APPROVED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3994442 |