

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/06/2016

Submitted Date:

12/15/2016

Document Number:

685200234**FIELD INSPECTION FORM**
 Loc ID 326580 Inspector Name: LABOWSKIE, STEVE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Beebe, Sabre		sabre.beebe@bp.com	<a href="#">All Inspections</a>
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258261	WELL	PR	02/01/2001	GW	067-08344	MCMAHAN 2	PR

**General Comment:**[Complaint inspection in response to noise complaint \(200440584\), low frequency sound survey at complainant residence per Rule 802.d](#)

**Inspected Facilities**Facility ID: 258261 Type: WELL API Number: 067-08344 Status: PR Insp. Status: PR**Complaint**

Comment: SW Inspection Supervisor conducted a low frequency (c-scale) sound survey at complainant residence with 3M Soundpro DL sound meter (serial no. BGN010014 factory calibrated 6.6.16) with a calibrated calibrator used for pre and post calibrations. 3 surveys were run between 6:40 and 8:20 AM (a time that complainant stated noise was most noticeable). Conditions were overcast, calm winds with temperatures between 20 and 30 deg F. Ambient noise sources include vehicle traffic on nearby US 550 and aircraft around La Plata County/Animas Air Park airports. Averaged noise levels were consistently 59 or 60 db(c) 25' from the northwest or northeast corner of the residence in direction of equipment with soundmeter set on tripod 4' above ground level. Data report available via link on "attachement" page.

Corrective Action:

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685200234	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4034998">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4034998</a>
685200238	meter placement on NE corner of house towards wel	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4028877">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4028877</a>
685200239	meter display at end of survey showing 59 db(c)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4028878">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4028878</a>
685200240	sound survey data report	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4028879">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4028879</a>