



photo 1: Facing west toward the location along the access road.



photo 2: Well marker at the center of the location.



photo 3: West side of the location facing east.



photo 4: Facing northeast toward the location.



photo 5: Facing along the northeast side of the location.



photo 6: The vegetation has not adequately established at the northeast side of the location.



photo 7: East side of the location facing north.



photo 8: East side of the location facing southwest. Rock rip/rap is placed at the drainage.



photo 9: East side of the location facing northwest.



photo 10: Southeast side of the location facing northwest.