



photo 1: Facing west along the access road.



photo 2: Well signs at the location.



photo 3: Facing southeast toward the location.



photo 4: There was oil noticed on the engine skid.



photo 5: There is stained soil around the exhaust from the engine.