



photo 1: Facing west along the access road. Vehicle rutting is developing along the road.



photo 2: Facing southeast toward the location.



photo 3: Well signs at the location.



photo 4: South side of the location facing north. The pit is at the left side of photo.