



photo 1: There are signs of erosion along the access road near the location. Stormwater is not being directed toward the culvert.



photo 2: Facing west toward the well head.



photo 3: West side of the location facing east.



photo 4: Well signs at the location.



photo 5: Lined pit at the northeast side of the location.



photo 6: There appears to be tears in the pit liner.



photo 7: The lid was left off the buried container at the east side of the location.



photo 8: The insulation is outside of the sound wall near the well head.