



Photo 1: View of the project area from the northwestern corner facing center.



Photo 2: View of the western portion of the project area from the northwestern corner facing southward. Revegetation is largely comprised of grasses such as crested wheatgrass (*Agropyron cristatum*) and Intermediate wheatgrass (*Thinopyron intermedium*), and dropseed (*Sporobolus* sp.)



Photo 3: View of the northern portion of the project area from the southwestern corner facing eastward.



Photo 4: View of stormwater erosion occurring within the western portion of the project area.



Photo 5: Another view of stormwater erosion within the western portion of the project area.



Photo 6: View of trailer in the southern portion of the project area that needs to be removed.



Photo 7: View of area that is approximately 75 feet long and wide that has recently been disturbed and needs to be seeded.



Photo 8: View of the eastern portion of the project area from the southeastern corner facing northward.



Photo 9: View of some pin flags that are scattered around the well pad.



Photo 10: View of more pin flags that are scattered around the well pad. Several more were observed and need to be properly disposed of.