

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/20/2017

Submitted Date:

06/21/2017

Document Number:

666803260**FIELD INSPECTION FORM**

Loc ID 335541 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 1600 BROADWAY ST STE 2600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:18 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289392	WELL	PR	06/18/2011	GW	045-13754	O'Toole A1	PR
289393	WELL	PR	06/18/2011	GW	045-13753	O'Toole A2	PR
289394	WELL	PR	07/14/2007	GW	045-13752	O'TOOLE A3	PR
289395	WELL	PR	02/21/2007	GW	045-13751	O'TOOLE A4	PR
301931	WELL	PR	08/01/2012	GW	045-18327	O'Toole A6	PR
301932	WELL	PR	02/17/2012	GW	045-18328	O'Toole A7	PR
301933	WELL	PR	08/01/2012	GW	045-18329	O'Toole A5	PR
301934	WELL	PR	06/17/2011	GW	045-18330	O'Toole A8	PR
421530	WELL	PR	06/19/2011	GW	045-20400	O'Toole A9	PR

General Comment:[2017 Flowline NTO Inspection 1000' Buffer](#)

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift	# 9		
Comment:	39.522774/-107.663966		
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:	39.522590/-107.664254		
Corrective Action:		Date:	
Type: Flow Line	#		
Comment:	Not in use 1-3", 4-2" Marked with paint, see photo		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:	39.522529/-107.663520		
Corrective Action:		Date:	
Type: Flow Line	#		
Comment:	In use; 9-2" steel risers at wellhead, 30-2", 5-3", 1-1" risers at separators, 3-3", 1-1" risers at tanks, 1-1" gas feed to ECB		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 12		
Comment:	39.522560/-107.663897		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:	Centralized battery				
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		

Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLs	STEEL AST		39.522560,-107.664365	
Comment:						
Corrective Action:					Date:	
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities				
Facility ID:	289392	Type:	WELL	API Number: 045-13754 Status: PR Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:				Date:
Facility ID:	289393	Type:	WELL	API Number: 045-13753 Status: PR Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:				Date:
Facility ID:	289394	Type:	WELL	API Number: 045-13752 Status: PR Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:				Date:
Facility ID:	289395	Type:	WELL	API Number: 045-13751 Status: PR Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:				Date:
Facility ID:	301931	Type:	WELL	API Number: 045-18327 Status: PR Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:				Date:
Facility ID:	301932	Type:	WELL	API Number: 045-18328 Status: PR Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:				Date:
Facility ID:	301933	Type:	WELL	API Number: 045-18329 Status: PR Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:				Date:
Facility ID:	301934	Type:	WELL	API Number: 045-18330 Status: PR Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:				Date:

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
		Culverts	Pass			
Gravel	Pass					
Hydro Mulch	Pass					
		Gravel	Pass			
		Ditches	Pass			
Culverts	Pass					
		Rip Rap	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401315369	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4176865
666803265	URSA NTO	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4176863