



Photo 1: View of the project area from the northern edge facing center.



Photo 2: View of the northern portion of the project area from the northern edge facing westward. Revegetation is progressing, but weedy in portions. Common species such as sagebrush (*Artemisia tridentata*), rubber rabbitbrush (*Chrysothamnus nauseosus*), western wheatgrass (*Pascopyrum smithii*), yellow mustard (*Systembrium altissimum*), and cheatgrass (*Bromus tectorum*).



Photo 3: View of fill slope in the eastern portion of the project area from the northern edge facing westward.



Photo 4: View rig anchor cable in the northeastern portion of the project area facing westward.



Photo 5: View of erosional channel approximately 2.5 feet wide and deep on the eastern edge of the working area.



Photo 6: View of erosional channel downstream of Photo 5, in fill slope.