

Inspection Photos
Location Name: Federal Plover #28-5 X
API: 05-123-20126



Photo from prior inspection for comparison



Photo 1: Bradenhead not plumbed to surface.



Inspection Photos
Location Name: Federal Plover #28-5 X
API: 05-123-20126



Photo from prior inspection for comparison



Photo 2: Deadman unmarked

Inspection Photos
Location Name: Federal Plover #28-5 X
API: 05-123-20126



Photo from prior inspection for comparison




Photo 3: No emergency contact number at wellhead



Inspection Photos
Location Name: Federal Plover #28-5 X
API: 05-123-20126



Photo from prior inspection for comparison



Photo 4: Stained soil at engine