

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/23/2017

Submitted Date:

11/06/2017

Document Number:

680402083**FIELD INSPECTION FORM**

Loc ID 316810 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num:

Operator Information:OGCC Operator Number: 56680Name of Operator: MERRION OIL & GAS CORPAddress: 610 REILLY AVENUECity: FARMINGTON State: NM Zip: 87401**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Thompson, Philana	(505) 324-5300	pthompson@merrion.bz	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
		mike.leonard@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232871	WELL	PR	09/01/2014	GW	113-06060	COCKLEBUR DRAW UNIT 3	SI

General Comment:

Location			
Lease Road:			
Type	Main		
comment:	BLM surface		
Corrective Action	L		Date:
Type	Access		
comment:	Gravel road with washed out and pothole areas		
Corrective Action	L		Date: 11/27/2017
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign located at on road at W. side of pad.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused scrap pipe on north side of pad removed as required CA on inspection Doc#680401075 and submitted with FIRR Doc#401176818 on 1/3/2017.		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Pipe barricade around wellhead.		
Corrective Action:			Date:
Equipment:			
Type: Flow Line	# 1		corrective date
Comment:	Flow line to facilities ~.5 mi. NW.		
Corrective Action:			Date:
Type: Deadman # & Marked	# 2		
Comment:	One marked. One unmarked. See attached photos.		
Corrective Action:	Mark guy line anchors per Rule 604.c.(2)Q.		Date: 11/28/2017
Venting:			

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 232871 Type: WELL API Number: 113-06060 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Well shut in 12/2015.
No current MIT on record or delinquent as required by Rule 326.

Corrective Action: Contact dnr_cogccengineering@state.co.us with resolution plan.Date: 11/17/2017

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Compaction	Pass			

Comment: [Location covered in vegetation.](#)

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680402110	Inspection photos 10/23/2017	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4295490