

Inspection Photos



Photo 1. Facing northwest along the access road. The road was in the process of being graded and soil was being pushed onto the road.

Inspection Photos



Photo 2. Soil was being pushed onto the road from the road side. The soil is loose and susceptible to erosion.

Inspection Photos



Photo 3. The arrow points to the side of the road where soil is being pushed onto the road which is also causing the road to become widened.

Inspection Photos



Photo 4. The vehicle shows the size of the access road. The road needs to be maintained to prevent widening of the road.

Inspection Photos



Photo 5. Facing northwest toward the location.

Inspection Photos



Photo 6. West side of the location facing southeast. The location was recently graded.

Inspection Photos



Photo 7. The diversion ditch was installed along the south side of the location.

Inspection Photos



Photo 8. A diversion ditch was created for stormwater diversion. This disturbance is susceptible to erosion and no other BMP's are installed.