

Inspection Photos
Location Name: Pauline #5
API: 05-123-12903



Photo 1: Location, looking NE. Berms are earthen in floodplain.



Photo 2: Wellhead, looking SE

Inspection Photos
Location Name: Pauline #5
API: 05-123-12903



Photo from J Gomez's prior inspection for comparison



Photo 3: NFPA label replaced.

Inspection Photos
Location Name: Pauline #5
API: 05-123-12903



Photo 4: Separator is not properly anchored in floodplain.