

Location Name: XTO API 103-10111

1/02/2018



Tank base and bottom looking west



Stained gravel in SPCC looking south

XTO 103-10111

Inspection 1/02/2018



Electric tank heater removed for testing



Tank with bottom missing. Tank has been moved from accident area