

Inspection Photos

API: 05-067-06559

Operator: BP AMERICA PRODUCTION COMPANY

Inspection Number: 680602407

Inspection Date: 1/4/2018



Photo 1. View of the northern portion of the project area from the northeastern corner facing westward.



Photo 2. View of the eastern portion of the project area from the southeastern edge facing northward, revegetation is progressing within this portion of the interim reclamation area.



Photo 3. View of the southern portion of the interim reclamation area from the southeastern edge facing westward. Vegetation in this area is largely annual weeds such as yellow tumblemustard (*Sysimbrium altissimum*). This needs to be evaluated during the 2018 growing season and re-seeded by November 1, 2018 if desirable cover is not established.



Photo 4. View of Russian thistle (*Salsola tragus*) debris within the southern portion of the project area.



Photo 5. View of Russian thistle debris in the northern portion of the project area.



Photo 6. View of musk thistle (*Carduus nutans*) within the project area.



Photo 7. View of sign at the entrance to the well pad.