FORM INSP Rev

X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Facility Name

CENTRICOM STATE 11-16

Inspection Date:

03/07/2018
Submitted Date:

03/07/2018
Document Number:

675000227

Insp Status

PR

FIELD INSPECTION FORM

Loc ID Inspector Name: On-Site Inspection			On-Site Inspection	Star	tus Summary:			
335792	335792 Duran, Alicia		2A Doc Num:		THIS IS A FOLLOW UP INSPECTION			
Operator Info	rmation:	<u> </u>			FOLLOW UP INSPECTION REQUIRED			
OGCC Operat	or Number: 10	0110		X	NO FOLLOW UP INSPECTION REQUIRED			
Name of Opera	ator: GREAT WEST	ERN OPER	RATING COMPANY LL	C Fine	Findings:			
Address: 1801 BROADWAY #500					Number of Comments 0 Number of Corrective Actions			
City:DENVER State:CO Zip:80202				80202	Corrective Action Response Requested			
Contact Information:								
Contact Name P		Phone	Email		Comment			
,			cogccinspe m	ctions@gwogco.co	co All Inspections			
Inspected Facilities:								

Well Class

GW

API Num

001-09466

General	Comment:

Type

WELL

Status

 PR

Status Date

01/21/2013

Facility ID

266810

	<u>Location</u>								
Overall Good: 🔀									
Signs/Marker:									
Туре	WELLHEAD								
Comment:									
Corrective Action:		Date:							
Туре	TANK LABELS/PLACA	TANK LABELS/PLACARDS							
Comment:									
Corrective Action:		Date:							
Туре	BATTERY								
Comment:									
Corrective Action:					Date				
Emergency Contact N	Number:								
Comment:									
Corrective Action:					Date:				
Overall Good: 🔀									
Spills:									
Туре	Area	Volume							
In Containment: N	No								
Comment:									
Multilple Spills and Releases?									
Fencing/:									
Туре	IGNITOR/COMBUSTO	R							
Comment:	Chain link								
Corrective Action:									
Туре	SEPARATOR								
Comment:	Chain link								
Corrective Action:	on:								
Type TANK BATTERY									
Comment:	: Chain link								
Corrective Action:	Date:								
Туре	Type WELLHEAD								
Comment:	Comment: Chain link								
Corrective Action: Date:									
Equipment:	Equipment: corrective date								
Type: Emission Contr	ol Device	# 1							
Comment:									
Corrective Action:					Date:				
Type: Bird Protectors		# 2							

Inspector Name: Duran, Alicia Comment: Corrective Action: Date: Type: Gas Meter Run # 1 Comment: Corrective Action: Date: Type: VRU # 1 Comment: Corrective Action: Date: Type: Horizontal Heated Separator # 1 Comment: Corrective Action: Date: Type: Plunger Lift # 1 Comment: Corrective Action: Date: Type: Ancillary equipment # 1 Comment: Scrubber Corrective Action: Date: Type: Pig Station # 1 Comment: Corrective Action: Date: Tanks and Berms: Contents Capacity Type Tank ID SE GPS PRODUCED WATER OTHER **PBV FIBERGLASS** 1 Comment: 210 BBLS Corrective Action: Date: **Paint** Condition Adequate Other (Content) Other (Capacity) Other (Type) <u>Berms</u> Type Capacity Permeability (Wall) Permeability (Base) Maintenance Metal Adequate Walls Sufficent Base Sufficient Adequate Shared berm with crude oil tanks Comment: Corrective Action: Date: Tank ID SE GPS Contents Capacity Type CRUDE OIL 5 **OTHER** STEEL AST 39.961820,-104.897550 Comment: 286 BBLS Corrective Action: Date: Paint

Inspector Name: Duran, Alicia Condition Adequate Other (Content) Other (Capacity) Other (Type) **Berms** Capacity Permeability (Wall) Permeability (Base) Туре Maintenance Metal Adequate Walls Sufficent **Base Sufficient** Adequate Comment: Corrective Action: Date: Venting: Yes/No NO Comment: Corrective Action: Date: Flaring: Туре Comment: Corrective Action: Date:

Facility ID: 266810 Type: WELL API Number: 001-09466 Status: PR Insp. Status: PR Producing Well Comment: PR Corrective Action: Date: Comment: Plumbed to surface Corrective Action: Date:	meposter rame. But	,		Inspected	d Facilities				
Comment: PR Corrective Action: Date: BradenHead Comment: Plumbed to surface	Facility ID: 26681	0 Type:	WELL	API Number:	001-09466	Status: _	PR	Insp. Status:	PR
Corrective Action: BradenHead Comment: Plumbed to surface				Produc	ing Well				
BradenHead Comment: Plumbed to surface								_	
Comment: Plumbed to surface	Corrective Action:							Date:	
				Brade	nHead				
Corrective Action: Date:	<u>Comment</u> :	Plumbed to s	urface						
	Corrective Action:							Date:	

Inspector Name: Duran, Alicia **Environmental**

Spill/Ren	nedi	ution:	
Comme			
Correcti Action:			Date:
Emission	Cor	rol Burner (ECB): YES	
Commen	t:		
Pilot:	10	Wildlife Protection Devices (fired vessels): YES	

Reclamation - Storm Water - Pit								
Storm Water:								
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment		
Gravel	Pass	Gravel	Pass					
Comment:								
Corrective Action: Da						Date:		
Pits: NO SURFACE INDICATION OF PIT								

Attached Documents

You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:

Document Num	Description	URL
401566104	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4396066
675000228	Photos of tank battery and wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4396060

Date Run: 3/14/2018 Doc [#675000227]