

Location

Lease Road:			
Type	Access		
comment:	Road to well has been plowed over.		
Corrective Action			Date:

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	IGNITOR/COMBUSTOR		
Comment:	Iron panel fencing around 2 - 30" ECD's.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Iron panel fencing around wellhead.		
Corrective Action:			Date:

Equipment:				corrective date
Type: Plunger Lift	# 1			
Comment:				
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 1			
Comment:	Commingles w/ Linhart 3-33			
Corrective Action:				Date:
Type: Emission Control Device	# 2			
Comment:	East: 30" ECD for Tank VOC's. West: 30" ECD for Tank VOC's.			
Corrective Action:				Date:

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		,
Comment:	Shares berms with produced oil tanks.				

Corrective Action:						Date:	
<u>Paint</u>							
Condition		Adequate					
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	1	300 BBLs	STEEL AST		40.362805,-104.790499		
Comment:						Shares berms w/ produced oil & produced H2O tanks.	
Corrective Action:						Date:	
<u>Paint</u>							
Condition		Adequate					
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	1	200 BBLs	STEEL AST				
Comment:						Shares berms w/ produced oil & produced H2O tanks. Paint beginning to peel on the 200 Bbls. oil production tank.	
Corrective Action:						Date:	
<u>Paint</u>							
Condition		Adequate					
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:							
Corrective Action:						Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 245593 Type: WELL API Number: 123-13388 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Comment: Bradenhead plumbed to surface.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401582199	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4409825
691200021	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4409821