

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/21/2018

Submitted Date:

03/26/2018

Document Number:

685304517**FIELD INSPECTION FORM**

Loc ID 333625 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**26 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|--------------|---------------------|---------------------------------------|
| Beebe, Sabre | 970-779-9398 | Sabre.Beebe@bp.com | SW Inspection Reports |
| Inspections, All | | SanJuanCOGCC@bp.com | SW Inspection Reports |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 216088 | WELL | PR | 01/23/1992 | GW | 067-07694 | JONES 34-16 1 | PR |
| 297201 | WELL | PR | 04/18/2010 | GW | 067-09601 | JONES 34-16 3 | PR |

General Comment:[Inspection completed as routine inspection requirement.](#)[This inspection does not alleviate requirement to complete any open corrective actions from previous inspections.](#)[See link at end of report for path to downloadable pictures.](#)

Location

| | | | |
|--------------------|------------------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Dirt and gravel access road. | | |
| Corrective Action | L | Date: | |

Overall Good: ☐

| | | | |
|----------------------|---|-------|--|
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Stand alone sign at produced water tank. | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Stand alone sign at entrance to location. Sign is peeling and will need to be replaced. | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: Operator contact information posted on wellhead sign.

Corrective Action:

Date: _____

Overall Good: ☐

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|--|-------|--|
| Fencing/: | | | |
| Type | PUMP JACK | | |
| Comment: | Steel mesh safety barrier. | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Stock panel fencing. | | |
| Corrective Action: | | Date: | |
| Type | SEPARATOR | | |
| Comment: | Stock panel fencing. Includes gas meter run and production tank. | | |
| Corrective Action: | | Date: | |
| Type | LOCATION | | |
| Comment: | Post and wire fencing. | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|----------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Ancillary equipment | # 2 | | |
| Comment: | Telemetry equipment. | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|--|--|-------|
| Type: Other | # 1 | | |
| Comment: | Sound walls. | | |
| Corrective Action: | | | Date: |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Electrical control equipment. | | |
| Corrective Action: | | | Date: |
| Type: Gas Meter Run | # 2 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Ancillary equipment | # 2 | | |
| Comment: | Wellhead. | | |
| Corrective Action: | | | Date: |
| Type: Flow Line | # 2 | | |
| Comment: | #1 In use - 4" steel line from wellhead casing and tubing to separator inlet. All points co-located In use - 3" steel line from separator outlet to gas meter inlet. All points co-located. | | |
| Corrective Action: | | | Date: |
| Type: Compressor | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Horizontal Heated Separator | # 2 | | |
| Comment: | Single steel building double system. | | |
| Corrective Action: | | | Date: |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Electrical supply equipment. | | |
| Corrective Action: | | | Date: |
| Type: Flow Line | # 2 | | |
| Comment: | #3 In use - 4" steel line from wellhead casing and tubing to separator inlet. All points co-located. In use - 3" steel line from separator outlet to gas meter inlet. All points co-located. | | |
| Corrective Action: | | | Date: |
| Type: Prime Mover | # 1 | | |
| Comment: | Electric motor. | | |
| Corrective Action: | | | Date: |
| Type: Bird Protectors | # 1 | | |
| Comment: | Tank. | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| | | | | | | |
|--|---|----------|-----------|---------|--------|--|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 1 | OTHER | PBV STEEL | | , | |
| Comment: Partially buried 95 BBL steel tank with vent stack. | | | | | | |
| Corrective Action: | | | | | Date: | |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | 95 BBLS | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected FacilitiesFacility ID: 216088 Type: WELL API Number: 067-07694 Status: PR Insp. Status: PR**Producing Well**Comment: [PR - Review of electronic well file indicates last reported production as Dec 2017.](#)

Corrective Action:

Date:

Facility ID: 297201 Type: WELL API Number: 067-09601 Status: PR Insp. Status: PR**Producing Well**Comment: [PR - Review of electronic well file indicates last reported production as Dec 2017.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: [Revegetation of interim reclamation area is progressing with established grass.](#)**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Waddles | Pass | Culverts | Pass | | | |
| Compaction | Fail | Compaction | Pass | | | |
| Gravel | Fail | Gravel | Pass | | | |

Comment: Erosion channel in SE corner perimeter (off left side of riser). Channel is 4" - 6" wide and 2" - 6" deep. Erosion gulley in SE corner of location starting at edge of location. Gulley is 18" - 30" wide and 6' - 30" deep. Waddles along E perimeter fencing have deteriorated. Waddles no longer needed should be removed to clean up netting debris.

Corrective Action: Install or repair required BMPs to comply with Rule 1002.f.

Date: 04/26/2018

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401586989 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4414051 |
| 685304544 | Inspection pictures. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4414035 |