

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/17/2018

Submitted Date:

04/20/2018

Document Number:

680102873

FIELD INSPECTION FORM

Loc ID: 324472 Inspector Name: Colby, Lou On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 77330
Name of Operator: SG INTERESTS I LTD
Address: 100 WAUGH DR SUITE 400
City: HOUSTON State: TX Zip: 77007

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
		inspection@sginterests.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275739	WELL	XX	01/27/2018	GW	051-06060	Federal 11-90-26 1	CI

General Comment:

This is a Construction and Stormwater Inspection. Form 42 : NOTICE OF CONSTRUCTION: was filed for this site, start date 4/9/2018. Conditions at time of Inspection were overcast skies at 48 degrees F. Elevation at Site is 7,507 ft.

Location Construction

Location ID: 324472 CDP: _____

Comment: This construction is an expansion of the Pad surface of a built Location. Pad is being enlarged to the South so that the access road (leading to McIntyre Flowback Pits) once skirting the Southern Pad edge now cuts through the Location. Material has been taken from North & East cut slopes to build up expansion.

Corrective Action: _____ **Date:** _____

Form 2A COAs:

Comment: Equipment has been removed from Location; put in temporary storage to prepare for pad expansion and re-entry in well.

Corrective Action: _____ **Date:** _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____ **Date:** _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
SILT FENCES	Yes		

Comments: Erosion BMPs: Silt fence is installed as perimeter control along south side of site.
Other BMPs: _____

Corrective Action: _____ **Date:** _____

RETENTION PONDS	Yes		
Comments: Erosion BMPs: <input type="text" value="sediment traps"/>			
Other BMPs: <input type="text"/>			
Corrective Action: _____			Date: _____
SLOPE ROUGHENING	Yes		
Comments: Erosion BMPs: <input type="text"/>			
Other BMPs: <input type="text"/>			
Corrective Action: _____			Date: _____
DITCHES	Yes		
Comments: Erosion BMPs: <input type="text"/>			
Other BMPs: <input type="text"/>			
Corrective Action: _____			Date: _____
WADDLES	Yes		
Comments: Erosion BMPs: <input type="text" value="One Wattle is installed at break midpoint in silt fence; this BMP may be inadequate to control any significant amounts of run off/sediment & should be monitored. Refer to Photos attached."/>			
Other BMPs: <input type="text"/>			
Corrective Action: _____			Date: _____

Comment:

Corrective Action: **Date:** _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected FacilitiesFacility ID: 275739 Type: WELL API Number: 051-06060 Status: XX Insp. Status: CI**COGCC Comments**

Comment	User	Date
Construction Foreman indicated that Construction activities would likely be complete by day end.	colbyl	04/20/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680102874	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4441271