

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/04/2018

Submitted Date:

06/05/2018

Document Number:

689701412**FIELD INSPECTION FORM**Loc ID 324193 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10163Name of Operator: NONSUCH NATURAL GAS INCAddress: P O BOX 110066City: NAPLES State: FL Zip: 34108**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name  | Phone        | Email                    | Comment |
|---------------|--------------|--------------------------|---------|
| Lee, David    | 239-289-9046 | dlee@nng.us.com          |         |
| Spencer, Stan |              | stan.spencer@state.co.us |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 263296      | WELL | PR     | 08/15/2002  | GW         | 045-08120 | CSOC 697-12 1 | PR          |
| 292476      | PIT  | AC     | 09/27/2007  |            | -         | CSOC 697-12 1 | AC          |

**General Comment:**

**Location**

|                    |                             |       |  |
|--------------------|-----------------------------|-------|--|
| <b>Lease Road:</b> |                             |       |  |
| Type               | Access                      |       |  |
| comment:           | Continue routine maintenace |       |  |
| Corrective Action  | L                           | Date: |  |

Overall Good: ☐

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | BATTERY              |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |

|                           |  |             |
|---------------------------|--|-------------|
| Emergency Contact Number: |  |             |
| Comment:                  |  |             |
| Corrective Action:        |  | Date: _____ |

|                           |  |       |            |
|---------------------------|--|-------|------------|
| <b>Good Housekeeping:</b> |  |       |            |
| Type                      | WEEDS  |       |            |
| Comment:                  | Weeds on location, around equipment and pit. |       |            |
| Corrective Action:        | Comply with Rule 603.f .                     | Date: | 06/15/2018 |

Overall Good: ☐

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

|                    |              |       |  |
|--------------------|--------------|-------|--|
| <b>Fencing/:</b>   |              |       |  |
| Type               | TANK BATTERY |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |
| Type               | WELLHEAD     |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |
| Type               | SEPARATOR    |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |

|                                   |     |  |  |                 |
|-----------------------------------|-----|--|--|-----------------|
| <b>Equipment:</b>                 |     |  |  | corrective date |
| Type: Horizontal Heated Separator | # 1 |  |  |                 |
| Comment:                          |     |  |  |                 |
| Corrective Action:                |     |  |  | Date:           |
| Type: Dehydrator                  | # 1 |  |  |                 |
| Comment:                          |     |  |  |                 |
| Corrective Action:                |     |  |  | Date:           |
| Type: Plunger Lift                | # 1 |  |  |                 |
| Comment:                          |     |  |  |                 |
| Corrective Action:                |     |  |  | Date:           |
| Type: Bird Protectors             | # 2 |  |  |                 |
| Comment:                          |     |  |  |                 |
| Corrective Action:                |     |  |  | Date:           |

**Tanks and Berms:**

|                    |   |          |           |         |        |       |
|--------------------|---|----------|-----------|---------|--------|-------|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS |       |
| CONDENSATE         | 1 | 300 BBLS | STEEL AST |         | ,      |       |
| Comment:           |   |          |           |         |        |       |
| Corrective Action: |   |          |           |         |        | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     |             |

|                    |   |          |           |         |        |       |
|--------------------|---|----------|-----------|---------|--------|-------|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS |       |
| METHANOL           | 1 | <50 BBLS | STEEL AST |         | ,      |       |
| Comment:           |   |          |           |         |        |       |
| Corrective Action: |   |          |           |         |        | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|       |          |                     |                     |             |
|-------|----------|---------------------|---------------------|-------------|
| Type  | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |



|                      |                |                       |            |                  |
|----------------------|----------------|-----------------------|------------|------------------|
| Inspected Facilities |                |                       |            |                  |
| Facility ID: 263296  | Type: WELL     | API Number: 045-08120 | Status: PR | Insp. Status: PR |
| Producing Well       |                |                       |            |                  |
| Comment:             | Producing well |                       |            |                  |
| Corrective Action:   |                |                       |            | Date:            |
|                      |                |                       |            |                  |
| Facility ID: 292476  | Type: PIT      | API Number: -         | Status: AC | Insp. Status: AC |
|                      |                |                       |            |                  |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs                          | Chemical BMP Maintenance | Comment                                 |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---|
|                  |                 |                         |                       | Material Handling And Spill Prevention | Pass                     |   |
| Compaction       | Pass            |                         |                       |  |                          |   |
| Berms            | Pass            |                         |                       |  |                          |   |
| Gravel           | Pass            |                         |                       |  |                          |   |
|                  |                 | Ditches                 |                       |  |                          |   |
|                  |                 | Drains                  | Fail                  |  |                          | washing / erosion<br>39.53332 107.17609 |

Comment: Washing of ruts on road coming on to entrance of location.Corrective Action: Install or repair required BMPs per Rule 1002.f.Date: 07/06/2018**Pits:** ☐ NO SURFACE INDICATION OF PITType: Skimming/SettlingLined: YESPit ID: 292476Lat: 39.532900Long: -108.175600

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**Liner Type: \_\_\_\_\_ Liner Condition: InadequateComment: 2 tears found in pit. Near bottom of north west pit wall and at top of north east pit wall.

Corrective Action

Pit liner compromised (Rule 904). Reduce fluid level in pit, contact COGCC EPS staff for directives.Date: 06/06/2018c**Fencing:**Fencing Type: Netting/Fence.comFencing Condition: Adequate

Comment: \_\_\_\_\_

Corrective Action

Date: \_\_\_\_\_

**Netting:**Netting Type: Fence/Net ComboNetting Condition: Good

Comment: \_\_\_\_\_

Corrective Action

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_

Oil Accumulation: NO2+ feet Freeboard: YES

Comment: \_\_\_\_\_

Corrective Action

Date: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 401663079    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4484377">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4484377</a> |

|           |                                   |   |
|-----------|-----------------------------------|---|
| 689701414 | Inspection 689701412<br>photo log | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4484376">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4484376</a> |
|-----------|-----------------------------------|---|

