

**GR 32-34**  
**API# 05-045-06813**  
**Inspection# 689701748**



**Well photo.**

**GR 32-34**  
**API# 05-045-06813**  
**Inspection# 689701748**



**Sediment build up in location ditch**

**GR 32-34**  
**API# 05-045-06813**  
**Inspection# 689701748**



**Sediment washing on to location.**



**Erosion of north east hill side.**

**GR 32-34**  
**API# 05-045-06813**  
**Inspection# 689701748**



**Erosion of check dam and sediment build up.**

**Erosion of check dam and sediment build up.**

**GR 32-34**  
**API# 05-045-06813**  
**Inspection# 689701748**



**Damaged and unmaintained bales along south base of well pad.**

**GR 32-34**  
**API# 05-045-06813**  
**Inspection# 689701748**



**Damage and erosion of access road.**