

Inspection Photos  
Location Name: State 12-2  
API: 05-057-06281



**Photo 1. Overview of location taken at entrance facing northeast.**

Inspection Photos  
Location Name: State 12-2  
API: 05-057-06281



Photo 2. Stained soil at wellhead.



Photo 3. Low berm.