

Inspection Photos

Location Name: Moyer 'A' - 612N56W / 29SESW

Location #: 317532



Photo #1

Moyer Unit 14-29 (API 05-123-07025) wellhead

Bradenhead needs plumbed to surface



Photo #2

Moyer Unit 14-29 wellsite sign



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Moyer 'A' - 612N56W / 29SESW

Location #: 317532



Photo #3

Moyer Unit Battery

Moyer 11-29, 13-29, 15-29, 3-32, 11-32 (UIC wells)
Moyer 10-29, 14-29, 16-29, 15-30, 16-30, 6-32
(Producing wells)



Photo #4

Moyer Unit H2O tanks



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Moyer 'A' - 612N56W / 29SESW

Location #: 317532



Photo #5
Moyer Unit Battery
Free Water Knockout



Photo #6
Moyer Unit
H2O pits



Inspection Photos

Location Name: Moyer 'A' - 612N56W / 29SESW

Location #: 317532



Photo #7

Moyer Unit H2O Knockout house

Trash & Debris



Photo #8

Moyer Unit H2O Knockout house

Stained soil

Inspection Photos

Location Name: Moyer 'A' - 612N56W / 29SESW

Location #: 317532



Photo #9

Moyer Unit H2O Knockout house

Trash, debris, & stained soil

From previous FIR



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources