

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/04/2018

Submitted Date:

09/05/2018

Document Number:

691200407**FIELD INSPECTION FORM**
 Loc ID 317532 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 7800Name of Operator: BEREN CORPORATIONAddress: 2020 N BRAMBLEWOOD STREETCity: WICHITA State: KS Zip: 67206**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**27 Number of Comments2 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Gul, Awais		gula@berexco.com	
Hanes, Shawn		sehanes4@icloud.com	
Reynolds, Rodney	(316) 337-8340	reynoldsr@berexco.com	<a href="#">AI inspections</a>
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
100573	PIT	AC	09/23/1999		-	MOYER "A"	AC
100574	PIT	AC	09/23/1999		-	MOYER "A"	AC
100575	PIT	AC	09/23/1999		-	MOYER "A" 1	AC
239238	WELL	PR	07/29/2014	OW	123-07025	MOYER UNIT 14-29	PR
433344	TANK BATTERY	AC	04/14/2009		-	MOYER 'A'-612N56W 29SESW	AC

**General Comment:**[This is a WELL & BATTERY Inspection. Follow-up to FIR #684905482 dated 6/1/2018.](#)

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	BATTERY			
Comment:				
Corrective Action:				Date:
Type	CONTAINERS			
Comment:				
Corrective Action:				Date:
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	OTHER			
Comment:	<p>Stained soil at valve fittings, around vessels, in treater house, see pictures. Refer to rule 603.f. Properly treat or dispose of oily waste in accordance with Rule 907.e.</p> <p>Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.</p> <p>This CA was referenced in FIR# 684905482 dated 6/1/2018. The original CA date remains applicable.</p>			
Corrective Action:	Comply with Rules 603.f, 605.d, & 907.e.			Date: <u>07/02/2018</u>
Type	TRASH			
Comment:	<p>Trash in separator, knockout, injection pumphouse house.</p> <p>This CA was referenced in FIR# 684905482 dated 6/1/2018. The original CA date remains applicable.</p>			
Corrective Action:	Comply with rule 603.f.			Date: <u>07/03/2017</u>
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Iron mesh panel		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Iron rod fence		
Corrective Action:		Date:	
Type	PIT		
Comment:	Iron mesh panel		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron mesh panel		
Corrective Action:		Date:	

  

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment:	1.) Electric motor drives pump jack. 2.) Electric motor drives triplex injection pump.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	At well: 1 - chem. pump / drum w/ drip tray 1 - drum to bleed fluid		
Corrective Action:		Date:	
Type: Ancillary equipment	# 7		
Comment:	7 - chemical pumps w/ drums/tanks & drip trays.		
Corrective Action:		Date:	
Type: FWKO	# 1		
Comment:	140 Bbls. capacity		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	4/4-marked.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	1.) Triplex injection pump to inject into injection wells.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment: <a href="#">This centralized battery serves 14 locations (317535, 405727, 317531, 317533, 317536, 317528, 317530, 317532, 317529, 317526, 317525, 317534, 317538, 317537). Refer also to Tank Battery Facility ID #433344.</a>					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	FIBERGLASS AST		40.980504,-103.661013
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: <a href="#">Shares berms with 6 - 300 Bbls. produced H2O tanks &amp; FWKO.</a>				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	400 BBLS	FIBERGLASS AST		40.980338,-103.661201
Comment: <a href="#">Used as a gunbarrel skimming tank.</a>					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	Produced H2O / Crude Oil
Other (Capacity)	
Other (Type)	

Berms

Inspector Name: Evins, Bret

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Shares berms with 5 - Produced oil tanks.					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	5	300 BBLS	STEEL AST		40.980338,-103.661201
Comment:					
Corrective Action:				Date:	
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Shares berms with 400 Bbls. Produced oil / H2O Gunbarrel skimming tank.					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	6	300 BBLS	FIBERGLASS AST		40.980504,-103.661013
Comment:					
Corrective Action:				Date:	
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Shares berms with 200 Bbls. produced H2O tank & FWKO.					
Corrective Action:				Date:	
<u>Venting:</u>					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
<u>Flaring:</u>					
Type					
Comment:					
Corrective Action:					Date:



**Inspected Facilities**

Facility ID: <u>100573</u>	Type: <u>PIT</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>AC</u>
Facility ID: <u>100574</u>	Type: <u>PIT</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>AC</u>
Facility ID: <u>100575</u>	Type: <u>PIT</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>AC</u>
Facility ID: <u>239238</u>	Type: <u>WELL</u>	API Number: <u>123-07025</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>433344</u>	Type: <u>TANK</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>AC</u>

**Producing Well**

Comment: <u>PR.</u>	
Corrective Action:	Date:

**BradenHead**

Comment: <u>Bradenhead is NOT plumbed to surface. Foreman advised they will have bradenhead plumbed before the end of SEP 2018.</u>	
Corrective Action:	Date:

## Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Stormwater erosion has been addressed. This CA was referenced in FIR# 684905482 dated 6/1/2018.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

Type: Emergency      Lined: \_\_\_\_\_      Pit ID: 100574      Lat: 40.979862      Long: -103.660615

Reference Point: \_\_\_\_\_      Other: \_\_\_\_\_      Length: \_\_\_\_\_      Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_      Liner Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: c**Fencing:**

Fencing Type: \_\_\_\_\_      Fencing Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_      Netting Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_      Oil Accumulation: NO      2+ feet Freeboard: YES

Comment: Multiple produced water pits. Foreman indicated only used for emergencies.

Corrective Action

Date: \_\_\_\_\_

Type: Emergency      Lined: \_\_\_\_\_      Pit ID: 100573      Lat: 40.980121      Long: -103.661084

Reference Point: \_\_\_\_\_      Other: \_\_\_\_\_      Length: \_\_\_\_\_      Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_      Liner Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: c**Fencing:**

Fencing Type: Livestock      Fencing Condition: Adequate

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_      Netting Condition: \_\_\_\_\_



Comment:				Date:
Corrective Action				
Anchor Trench Present:		Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>	
Comment:	<u>Multiple produced water pits. Foreman indicated only used for emergencies.</u>			Date:
Corrective Action				
Type: <u>Emergency</u>	Lined:	Pit ID: <u>100575</u>	Lat: <u>40.980183</u>	Long: <u>-103.660670</u>
Reference Point:	Other:	Length:	Width:	
<u>Lining:</u>				
Liner Type:		Liner Condition:		
Comment:				Date: <u>c</u>
Corrective Action				
<u>Fencing:</u>				
Fencing Type:		Fencing Condition:		
Comment:				Date:
Corrective Action				
<u>Netting:</u>				
Netting Type:		Netting Condition:		
Comment:				Date:
Corrective Action				
Anchor Trench Present:		Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>	
Comment:	<u>Multiple produced water pits. Foreman indicated only used for emergencies.</u>			Date:
Corrective Action				

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691200408	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4570793">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4570793</a>