

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type LOCATION

Comment: Security Chainlink

Corrective Action:

Date: _____

Equipment:

corrective date

Type: Plunger Lift # 1

Comment:

Corrective Action:

Date: _____

Type: Ancillary equipment # 1

Comment: RTU

Corrective Action:

Date: _____

Type: Gas Meter Run # 1

Comment: LOTO @ rupture pin

Corrective Action:

Date: _____

Type: Horizontal Heated Separator # 1

Comment:

Corrective Action:

Date: _____

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,

Comment:

Corrective Action:

Date: _____

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment: Shares berms with produced water tank.					
Corrective Action:				Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	CONCRETE SUMP/VAULT		,
Comment: 53 BBL vault					
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment: Shares berms with production tank.					
Corrective Action:				Date:	

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 203370 Type: WELL API Number: 001-08879 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well appears to have been shut in for an undisclosed amount of time. After speaking with the locations gas marketer, it appears that no gas has been sold since February 2016. COGCC is requesting an M.I.T. to ensure well construction integrity.

Corrective Action: Well must have a successful mechanical integrity test performed or plugged as directed by Rule 319 b (3)

Date: 08/31/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401739871	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4558112
691300448	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4558111